



AUTODESK
Instructables

Peugeot 3008 5008 Rear Footwell Storage Compartment Lid

By [x8rltd](#) in [WorkshopCars](#)

Published Apr 17th, 2024



Introduction: Peugeot 3008 5008 Rear Footwell Storage Compartment Lid



1 X REAR GLOVEBOX LID
PEUGEOT 3008 (07-16)
PEUGEOT 5008 (09-16)

Symptoms of Fault

Snapped, broken, collapsed storage lid. Frame of lid come away from carpet. Difficulty opening original lid due to poor design.

The Fault

The OEM storage lid is a poor design which is easily broken.

The original design of storage lids for the footwell glovebox are made from flimsy plastic, foam, fiberglass and carpet and easily snap, break or buckle when stood on.

When broken, the layers of fiberglass become loose and contaminate the carpet and when touched your skin may become red and irritated. It is also not safe to inhale and can be dangerous, especially for a family car which this is made for!

If you approach Peugeot, they will say the lids are not designed to be stood on, which is impossible due to the compartment's location. Peugeot will proceed to quote around £500 for the entire footwell storage compartment as they do not sell the lid separately.

The original lid is also poorly designed as it is difficult to open. The lid has no handle therefore you need to squeeze your fingers in the gap between the lid and the base.

The Solution

Install the X8R storage lid to save money and restore the look of your interior.

X8R's improved design storage lid for the rear footwell storage compartment looks the part and is made from MDF wood, it certainly improves the aesthetics of your vehicle's interior. The MDF is far stronger than the OEM mix of plastic, foam, fiberglass and carpet. It can easily withstand the weight of an adult.

The design also features a stainless steel handle so you can access the storage compartment far more easily than before.

Vehicles Affected

Peugeot 3008 T84 2007-2016

Peugeot 5008 T87 2009-2016

Associated part numbers:

7585XN, 7585XM

This lid is suitable for both the left and right hand-side storage compartments. It is suitable for left and right-hand drive models.

You Will Receive

1 x MDF wooden lid complete with stainless steel handle.

Supplies

You will not need any tools for this repair.

Step 1: Remove Old Lid



Remove the old lid from your storage compartment.

Step 2: Clean the Area

If you have suffered from a broken lid, we advise cleaning the surrounding carpeted area thoroughly. The original lid contains fibreglass and when exposed it can spread into the carpet. Vacuum the area as best as possible.

Step 3: Install the New Lid



Install the new lid by pressing it at an angle into the clips on the compartment.

This completes the repair. If you need any further guidance on this install or would like to purchase the parts shown please call us on +44 01843 446643 or email us at sales@x8r.co.uk. Please also check out our instruction guide on YouTube. www.x8r.co.uk Installation is carried out at installers risk, if unsure please contact us or a professional, X8R Ltd cannot be held responsible for any adverse result of installing this product or any injuries caused by install, if in doubt ask a professional. All images and texts are copyright X8R Ltd 2024.