


**AUTODESK**  
Instructables

## Vauxhall Corsa Clutch Assist Spring Repair Kit

By [x8rltd](#) in [WorkshopCars](#)

Published Jun 12th, 2024



### Introduction: Vauxhall Corsa Clutch Assist Spring Repair Kit



**HIGH STRENGTH CARBON STEEL**

**NEXT DAY DELIVERY AVAILABLE  
HIGH QUALITY, WILL NOT BREAK!**

#### Symptoms of Fault

Snapped clutch spring, hard to change gears, pedal drops to the floor, loss of biting point

## The Problem

*The poor quality spring situated high up in the clutch pedal box will often snap*

The standard spring installed from factory is poor quality and often snaps under pressure. It can also become detached from the back of the clutch pedal. The spring is also situated high up on the clutch box, causing unnecessary pressure on the spring. The spring snapping causes the clutch pedal to fall to the floor which in turn makes it challenging to change gears.

The original spring is time consuming to replace as the pedal box would need to be removed entirely making it an expensive repair if carried out by a garage. On average 5 hours+ would be quoted. The new spring would also be likely to snap so the repair would need to be carried out again and again.

## The Solution

*The X8R spring is the best quality spring on the market and will eliminate future clutch issues*

At X8R Ltd we have developed an improved clutch spring which is far superior than the original and will not snap. The spring is precision engineered from high strength carbon steel. It is finished with a corrosion-resistant coating for longevity.

The spring can be installed with no tools, no mechanical experience and in 2 minutes. The spring simply locates into two existing mating areas on the pedal box and immediately rectifies the poor clutch control.

We offer fast and free Royal Mail 1st Class shipping as well as next day delivery options for UK, and fast and reliable international shipping methods.

## Vehicles Affected

Vauxhall Corsa D 2006-2014

Vauxhall Corsa E 2014-2019

## You Will Receive

1 x Carbon steel clutch spring

## Supplies

No tools necessary.

## Step 1:



*This entire repair can be completed in situ, you will not need to remove the clutch pedal box or any components. It will take 2 minutes to install this item.*

Firstly identify the two areas where the clutch spring locates.

- 1) The hook on the underside of the clutch pedal
- 2) The moulded section next to the clutch pedal

## Step 2:



Hook one side of the clutch assist spring on the underside of the clutch pedal, whilst pressing the "U" shaped hook on the otherside of the spring into the moulded section next to the clutch pedal. It will click into place.

## Step 3:



This completes the repair. If you need any further guidance on this install or would like to purchase the parts shown please call us on +44 01843 446643 or email us at [sales@x8r.co.uk](mailto:sales@x8r.co.uk). Please also check out our instruction guide on YouTube. [www.x8r.co.uk](http://www.x8r.co.uk) Installation is carried out at installers risk, if unsure please contact us or a professional, X8R Ltd cannot be held responsible for any adverse result of installing this product or any injuries caused by install, if in doubt ask a professional. All images and texts are copyright X8R Ltd 2024.